CITY OF BALTIMORE WET WEA		Page 1 of 6				
Sewershed: OUTFALL	Company: REI/DRAYCO	Date: 09/30/2008				
Test Type: SMOKE	Ground Condition: Dry: X Damp:_ Wet:_	Supervisor: E.R.				
Manhole ID: S51II_036MH	Test ID: S1039-009	Notifications Made:X (Residents, Fire, 31				
ield Sketch: (Show all manholes with num	nbers, blower placement location, sandle locations, defect locations and photo		es, building addresses a			
1513 1511 1508 1509 1506 1507 1505 1503 1501 VIH	1509 1507 1505 1503 006MH	1508 1506 1504 1502 004MH	020M			
009_OB04_P01 009_OB03_P01 009_OB02_P01	034MH 1429 1427 1425 1428 1421 1419 1411 1411 1411	1422 1420 1418 1416 5 2 1414 5 1412	023 284.9 284.9			
009_OB01_P01	141	1410	N LINWOOD			
Legend Primary and Abandoned Sewers	140	1406				
Sewer Smoke Tested Sewer	140	1404	_ ~ \			
Manhole	14	1402				
Blower Location	036MH		SNO:			
Observation Location Area Not to Smoke Test Flow Basin Boundary Outfall Sewershed Boundary Plat Boundary		ver #1 II_036MH				

CITY OF BALTIMORE WET WEATHER CONSENT DECREE SMOKE AND DYED WATER TESTING FORM								Page 2 of 6					
Sewershed: OUTFALL Company: REI/DRAYCO							Date: 09/30/2008						
Test Type: SMOKE				Ground Condition: Dry: X Damp:_ Wet:_					Supervisor: E.R.				
Manhole ID: S51II_036MH				Test ID: S1039-009						_	aportioen z.it.		
Field S	Field Sketch: (Show all manholes with numbers, blower placement location, sandbag or isolation locations, street names, building addresses and locations, defect locations and photograph numbers)												
D ()	Dringgo Dringgo												
No.		Address		Type	Loca	ition	Sector	Area		Severity		Photo Number	
	1409 KEN	HILL AVE.		03	0	7	02	_	1	03	S	1039-009_OB01-P01.jpg	
	1421 KEN			03	0		02		1	03		1039-009_OB02-P01.jpg	
	1429 KEN			02	0		02		4	03		1039-009_OB03-P01.jpg	
	1431 KEN			02	0		02		0	03		1039-009_OB04-P01.jpg	
OBOT	TIOT KEN	111227112.		UZ.			02	<u> </u>		- 00	Ť		
-													
								<u> </u>					
								-					
											-		
											_		
				OF	SED.	\/ / \T	ION CO	DES		<u> </u>			
	Source	е Туре		UE	Loca			DES	<u> </u>	Sector		Severity	
01 Ms	ain Sewer	10 MH Frame	01	Paved C			Non-Pa	ved		Public	01	No Smoke	
	ervice Line	11 Storm Drain		Asphalt	, OI 10.	11			_	Private	02	Trace	
	eanout	12 Catch Basin		Paved C)ther		Alley	Juus	02	ı iivale	_	Moderate	
	ownspout	13 Storm MH		Drivewa			Golf Co	urse				Major	
	ea Drain	14 Storm Ditch		Sidewal		14		ui 3 C				major	
	vy. Drain	15 Excavation		Curb		<u> </u>	J. 1101						
	air. Drain	16 Water Line		Yard - F	ront								
	und. Drain	17 Tele. Pole		Yard - B									
	09 Bldg. Interior 18 Other				ide								
55 510	_gto1101	. 5 5 51				l	1		<u> </u>			l	

Unique Test ID: S1039-009 Date: 09/30/2008 Manhole ID: S51II_036MH

Defect No: OB01 Supervisor: E.R. Basin: Outfall

Location: 1409 KENHILL AVE.

Source Type: 03 Cleanout Sector: 02 Private

Location: 07 Yard - Front Severity: 03 Moderate Drainage Area: 1 ft²

Comments: Smoke is coming from an above grade cleanout with a broken cap.

SMOKE TEST PHOTOGRAPHS



Photograph No: OB01-P01 Filename: S1039-009_OB01-P01.jpg

Unique Test ID: S1039-009 Date: 09/30/2008 Manhole ID: S51II_036MH

Defect No: OB02 Supervisor: E.R. Basin: Outfall

Location: 1421 KENHILL AVE.

Source Type: 03 Cleanout Sector: 02 Private

Location: 07 Yard - Front Severity: 03 Moderate Drainage Area: 1 ft²

Comments: Smoke is coming from an above grade cleanout with a broken cap.

SMOKE TEST PHOTOGRAPHS



Photograph No: OB02-P01 Filename: S1039-009_OB02-P01.jpg

Unique Test ID: S1039-009 Date: 09/30/2008 Manhole ID: S51II_036MH

Defect No: OB03 Supervisor: E.R. Basin: Outfall

Location: 1429 KENHILL AVE.

Source Type: 02 Service Line Sector: 02 Private

Location: 07 Yard - Front Severity: 03 Moderate Drainage Area: 24 ft²

Comments: Smoke is coming from the edge of the sidewalk in front of 1429 Kenhill Ave.

SMOKE TEST PHOTOGRAPHS



Photograph No: OB03-P01 Filename: S1039-009_OB03-P01.jpg

Unique Test ID: S1039-009 Date: 09/30/2008 Manhole ID: S51II_036MH

Defect No: OB04 Supervisor: E.R. Basin: Outfall

Location: 1431 KENHILL AVE.

Source Type: 02 Service Line Sector: 02 Private

Location: 07 Yard - Front Severity: 03 Moderate Drainage Area: 40 ft² Comments: Smoke is coming from the edges and cracks in the sidewalk in front of 1431 Kenhill Ave.

SMOKE TEST PHOTOGRAPHS



Photograph No: OB04-P01 Filename: S1039-009_OB04-P01.jpg